



Assembly Instructions

Traveling Mary & Joseph Display

Traveling Mary and Joseph parts list



Joseph



Joseph's staff




Mary's halo




Mary's cloak




Donkey ears



Mary on donkey




Joseph's stand



Donkey hips



Five 1/4" x 1" nylon bolts



Five 1/4"-20 nylon wings nuts




Two #8 x 3/4" Flat head screws



Rope



Donkey rear legs



Donkey front legs

Assembly of Mary and Donkey

1. Attach Mary's cloak to front side (viewing side) of the donkey with four ¼" x 1" nylon bolts and four wing nuts.
2. Attach Mary's halo with two flat head #8 x ¾" screws.
3. Connect the donkey hips by sliding them into the slots of the donkey.
4. Slide the front and rear donkey legs into the notches on the hips.
5. Slide the donkey ears into the notch on the head of the donkey.
6. Tie the rope bridle onto the donkey's head.

Assembly of Joseph

1. Insert Joseph into slot of the stand.
2. Connect Joseph's staff to his hand using a ¼" x 1" nylon bolt and wing nut. The head of the bolt will fit into the pear shaped cutout on the staff.
3. Tie a rope to the donkey's bridle and connect it to Joseph's hand.
4. Tie a short piece of rope around Joseph's head.

Stake it down – Stake everything down – Then fasten to stakes with screws

1. The donkey requires a stake for each leg.
2. Joseph needs a stake for both sides out of view.



St. Margaret Mary Knights of Columbus Council 11091, 111 S. Hubbard St., Algonquin, IL 60102
Design and Image Copyright ©2005, 2007, 2010, 2011 and 2012.

<http://www.kcnativitysets.com>